

Tie in Design process.

This slide pack takes you through the following steps involved in designing a piping tie-in:

1. Destruct P&ID
2. Construct P&ID
3. Offshore site survey photographs
4. Existing layout CAD model
5. Proposed layout CAD model
6. Stress Isometrics drawings
7. Piping fabrication Isometrics drawings